

Under Review Notification

Raised By: Steven Drouin
 Date: 19.02.08

Product #: D412-724
 Product Name: HEAD REST

Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143) (eg. RBEM324U3010101-1)	Drawing or Document & <u>Current</u> Affected Revision for each part listed	"Y" or "N" Required for Each Part Do not leave blank							Reserved ECN / URF Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
		DO NOT SHIP	Red Tag/Quarantine Stock	Advise Customers	Hold all Production	Re-Work Stock	PP Under Review (Engineer Signoff Required.)	Put Product Specifications Under Review ("Bluefiles")		
D412--724-011	IIN-D412-724 REV A	Y	Y	N	Y	N	Y	Y	19-568	CHG#001
D3304-041	D3304 Rev B	Y	Y	N	Y	N	Y	Y	19-568	Revise Drawing
D3304-043	D3304 Rev B	Y	Y	N	Y	N	Y	Y	19-568	Revise Drawing
D3304-044	D3304 Rev B	Y	Y	N	Y	N	Y	Y	19-568	Revise Drawing

Description of Issue:

D3304-041/043/044 drawings needs to be revise to replacing BLBS-0016 pip pin with NAS1353DS7S13D pip pin's to comply with AD CF-91-29R1 for the 205A-1 and 212

See Enginnering for more information

Distribution:

VP Operations	Director of Engineering	Customer Support Manager	Technical Support
Director of Operations	Chief Engineer	Production Engineers	Product Manager - Solutions Provider
Director Quality Assurance	Engineering Project Managers	Production Planners	Supply Chain Director / Senior Buyer
QC Coordinator	Engineering Clerk	Purchasing Manager	Marketing Eugene